



Intel Firmware Vulnerability

List of affected FUJITSU Products

In an [advisory note](#) on May 1 2017, Intel published security information about an escalation of privilege vulnerability in Intel® Active Management Technology (AMT), Intel® Standard Manageability (ISM), and Intel® Small Business Technology. Reference: INTEL-SA-00075 or CVE-2017-5689

Last revised: 23 February 2018

Notes

- This list provides an overview of Fujitsu affected systems introduced since 2012.
- The vulnerability currently affects CCD products only.
- The list is regularly updated.

OEM Mainboards

Affected mainboards	New ME (w fix)	ME release date	New BIOS (w fix)	BIOS release date
D3061-B1	7.1.91.3272	May 29, 2017	not planned	not planned
D3062-B1	7.1.91.3272	May 29, 2017	not planned	not planned
D3071-S1	7.1.91.3272	May 29, 2017	not planned	not planned
D3076-S1	7.1.91.3272	May 29, 2017	not planned	not planned
D3128-B1	7.1.91.3272	May 29, 2017	not planned	not planned
D3162-B1	8.1.71.3608	May 19, 2017	not planned	not planned
D3128-B2	8.1.71.3608	May 19, 2017	not planned	not planned
D3221-B1	9.1.41.3024	May 08, 2017	not planned	not planned
D3231-S1	9.1.41.3024	May 08, 2017	not planned	not planned
D3236-S1	9.1.41.3024	May 08, 2017	not planned	not planned
D3243-S1	9.1.41.3024	May 08, 2017	not planned	not planned
D3348-B1	9.1.41.3024	May 08, 2017	not planned	not planned
D3348-B2	9.1.41.3024	May 08, 2017	not planned	not planned
D3401-B1	11.0.25.3001	May 04, 2017	R1.21.0	June 09, 2017
D3401-B2	11.6.29.3287	May 04, 2017	R1.8.0	May 31, 2017
D3402-B1	11.0.25.3001	May 04, 2017	R1.21.0	June 09, 2017
D3402-B2	11.6.29.3287	May 04, 2017	R1.8.0	May 31, 2017
D3410-B1	11.0.25.3001	May 04, 2017	R1.21.0	June 09, 2017
D3410-B2	11.6.29.3287	May 04, 2017	R1.8.0	May 31, 2017
D3417-B1	11.0.25.3001	May 04, 2017	R1.21.0	June 14, 2017
D3417-B2	11.6.29.3287	May 04, 2017	R1.8.0	May 19, 2017

D3433-S1	11.0.25.3001	May 04, 2017	R1.20.0	tbd
D3441-S1	11.0.25.3001	May 04, 2017	R1.20.0	tbd
D3445-K1	11.0.25.3001	May 04, 2017	tbd	tbd
D3446-S1	11.0.25.3001	May 04, 2017	R1.20.0	tbd
D3460-D1	11.6.29.3287	May 04, 2017	tbd	tbd

Desktop PC (ESPRIMO)

Affected model	New ME (w fix)	ME release date	New BIOS (w fix)	BIOS release date
ESPRIMO P9900	6.2.61.3535	July 07, 2017	not planned	not planned
ESPRIMO E9900	6.2.61.3535	July 07, 2017	not planned	not planned
ESPRIMO E700/P700	7.1.91.3272	May 19, 2017	not planned	not planned
ESPRIMO E900/P900	7.1.91.3272	May 19, 2017	not planned	not planned
ESPRIMO C700	7.1.91.3272	May 19, 2017	not planned	not planned
ESPRIMO E710/P710	8.1.71.3608	May 24, 2017	not planned	not planned
ESPRIMO E910/P910	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO Q910	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO C710/C910-L	8.1.71.3608	May 19, 2017	not planned	not planned
ESPRIMO X913/X913T	8.1.71.3608	May 24, 2017	not planned	not planned
ESPRIMO E720/P720	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO E920/P920/PH521	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO C720/Team PoS 7000S	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO X923/ESPRIMO X923-T	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO E520/ESPRIMO P520	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO Q920	9.1.41.3024	May 08, 2017	not planned	not planned
ESPRIMO P756	11.0.25.3001	May 04, 2017	R1.21.0	June 09, 2017
ESPRIMO P956	11.0.25.3001	May 04, 2017	R1.21.0	June 01, 2017
ESPRIMO Q956	11.0.25.3001	May 04, 2017	R1.21.0	June 09, 2017
ESPRIMO D756 (E85+;E90+;E94+)	11.0.25.3001	May 04, 2017	R1.21.0	June 01, 2017
ESPRIMO D956 (E85+;E90+;E94+;LL)	11.0.25.3001	May 04, 2017	R1.21.0	June 01, 2017
ESPRIMO X956	11.0.25.3001	May 04, 2017	R1.21.0	June 14, 2017
ESPRIMO P757 (E85+;E90+;E94+)	11.6.29.3287	May 04, 2017	R1.8.0	May 26, 2017
ESPRIMO P957 (E85+;E90+;E94+;POWER)	11.6.29.3287	May 04, 2017	R1.8.0	May 26, 2017
ESPRIMO Q957, MRE	11.6.29.3287	May 04, 2017	R1.8.0	May 26, 2017
ESPRIMO D757 (E85+;E90+;E94+)	11.6.29.3287	May 04, 2017	R1.8.0	June 01, 2017
ESPRIMO D957 (E85+;E90+;E94+)	11.6.29.3287	May 04, 2017	R1.8.0	June 01, 2017

Workstation (CELSIUS)

Affected model	New ME (w fix)	ME release date	New BIOS (w fix)	BIOS release date
CELSIUS W280	6.2.61.3535	July 07, 2017	not planned	not planned
CELSIUS W380/W480	6.2.61.3535	July 07, 2017	not planned	not planned
CELSIUS W410	7.1.91.3272	May 19, 2017	not planned	not planned
CELSIUS W510	7.1.91.3272	May 19, 2017	not planned	not planned
CELSIUS R920/R920 Power	7.1.91.3272	May 29, 2017	not planned	not planned
CELSIUS R930/R930 Power	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS M720/M720 Power	7.1.91.3272	May 19, 2017	not planned	not planned
CELSIUS M730/M730 Power	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS W420	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS W520	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS C620	8.1.71.3608	May 19, 2017	not planned	not planned
CELSIUS W530	9.1.41.3024	May 08, 2017	not planned	not planned
CELSIUS M740/M740 Power	9.1.41.3024	May 09, 2017	not planned	not planned
CELSIUS R940/R940 Power	9.1.41.3024	May 09, 2017	not planned	not planned
CELSIUS W550, W550 POWER	11.0.25.3001	May 04, 2017	R1.21.0	June 09, 2017
CELSIUS J550	11.0.25.3001	May 04, 2017	R1.21.0	June 01, 2017
CELSIUS J550/2	11.6.29.3287	May 04, 2017	R1.8.0	May 26, 2017
CELSIUS W570, POWER, POWER+	11.6.29.3287	May 04, 2017	R1.8.0	May 26, 2017

Mobile (LIFEBOOK/STYLISTIC/CELSIUS)

Affected model	New BIOS (w fix)	BIOS release date
LIFEBOOK T730	V1.09	July 17, 2017
LIFEBOOK E780; CELSIUS H700	V1.21	July 17, 2017
LIFEBOOK S760	V1.22	July 17, 2017
LIFEBOOK P770	V1.17	July 17, 2017
LIFEBOOK S710	V1.12	July 17, 2017
LIFEBOOK T900; Lifebook T900/B	V1.20	July 17, 2017
LIFEBOOK T731	V1.11	July 17, 2017
LIFEBOOK E751; LIFEBOOK E781; LIFEBOOK S751; LIFEBOOK S781	V1.23	July 17, 2017
LIFEBOOK S761; LIFEBOOK S561	V1.21	July 17, 2017
LIFEBOOK NH90/DN; CELSIUS H910	V1.17	July 17, 2017
CELSIUS H710	V1.18	July 17, 2017
LIFEBOOK P771	V1.18	July 17, 2017
LIFEBOOK T901	V1.18	July 17, 2017
LIFEBOOK E752; LIFEBOOK E782; LIFEBOOK S752; LIFEBOOK S782	V1.18	July 12, 2017
LIFEBOOK E752; LIFEBOOK E782; LIFEBOOK S752; LIFEBOOK S782 (Windows 8 models)	V2.16	July 12, 2017
LIFEBOOK S792	V1.13	July 12, 2017
LIFEBOOK S792 (Windows 8 model)	V2.14	July 12, 2017
LIFEBOOK E733/G; LIFEBOOK E733; LIFEBOOK E753/G; LIFEBOOK E753; LIFEBOOK E743/G; LIFEBOOK E743	V1.11	July 12, 2017
CELSIUS H720	V1.10	July 12, 2017
CELSIUS H720 (Windows 8 model)	V2.14	July 12, 2017
CELSIUS H920	V1.04	July 12, 2017
CELSIUS H920 (Windows 8 model)	V2.08	July 12, 2017
LIFEBOOK P772	V1.14	July 12, 2017
LIFEBOOK P772 (Windows 8 model)	V2.13	July 12, 2017
LIFEBOOK U772/E; LIFEBOOK U772	V1.11	July 12, 2017
LIFEBOOK U772; LIFEBOOK U772/F; LIFEBOOK U772/FW; LIFEBOOK U772/FX; LIFEBOOK U772/G; LIFEBOOK U772/GX (Windows 8 models)	V2.12	July 12, 2017
STYLISTIC Q702; STYLISTIC QH77/J; STYLISTIC WQ2/J; STYLISTIC Q702/F; STYLISTIC Q702/G	V2.22	July 12, 2017
LIFEBOOK T902	V1.06	July 13, 2017
LIFEBOOK T902; LIFEBOOK T902/F; LIFEBOOK T902/G (Windows 8 models)	V2.13	July 12, 2017
LIFEBOOK T732; LIFEBOOK T732/F	V1.11	July 12, 2017
LIFEBOOK E754/H; LIFEBOOK E744/H; LIFEBOOK E734/H; LIFEBOOK E754; LIFEBOOK E744; LIFEBOOK E734; FUTRO ME734; LIFEBOOK E754/K; LIFEBOOK E744/K; LIFEBOOK E734/K	V1.31	June 26, 2017
LIFEBOOK S904/H; LIFEBOOK S904; LIFEBOOK S904/J; LIFEBOOK S904/JX	V1.25	July 12, 2017
CELSIUS H730	V1.18	July 12, 2017
LIFEBOOK U904/H; LIFEBOOK U904	V1.16	July 12, 2017
ARROWS Tab WQ2/M; ARROWS Tab Q704/H; STYLISTIC Q704; ARROWS Tab Q704/PV	V1.38	June 26, 2017
LIFEBOOK T734/H; LIFEBOOK T734	V1.14	July 12, 2017
LIFEBOOK T904/H; LIFEBOOK T904	V1.17	July 12, 2017
LIFEBOOK S935/K; LIFEBOOK S935/KX; LIFEBOOK S935	V1.16	June 26, 2017
ARROWS Tab Q775/K; STYLISTIC Q775	V1.18	June 26, 2017

LIFEBOOK T725/K; LIFEBOOK T725	V1.18	June 26, 2017
LIFEBOOK T935/K; LIFEBOOK T935	V1.18	June 26, 2017
LIFEBOOK U745/K; LIFEBOOK U745/KX; LIFEBOOK U745; LIFEBOOK U745/M; LIFEBOOK U745/MX	V1.20	June 26, 2017
ARROWS Tab Q665/L; ARROWS Tab Q665/LX; STYLISTIC Q665; ARROWS Tab Q665/M	V1.13	June 26, 2017
LIFEBOOK E556/M; LIFEBOOK E546/M; LIFEBOOK E556; LIFEBOOK E546; LIFEBOOK E556/P; LIFEBOOK E546/P	V1.16	May 17, 2017
LIFEBOOK E756/M; LIFEBOOK E746/M; LIFEBOOK E736/M; LIFEBOOK E756; LIFEBOOK E746; LIFEBOOK E736; LIFEBOOK E756/P; LIFEBOOK E746/P; LIFEBOOK E736/P	V1.19	May 17, 2017
LIFEBOOK S936/M; LIFEBOOK S936/MX; LIFEBOOK S936; FUTRO MS936; LIFEBOOK S936/P; LIFEBOOK S936/PX	V1.15	May 18, 2017
CELSIUS H760	V1.19	May 17, 2017
ARROWS Tab Q736/M; STYLISTIC Q736; ARROWS Tab Q736/P	V1.12	May 18, 2017
LIFEBOOK T726/N; LIFEBOOK T726; LIFEBOOK T726/P	V1.13	May 17, 2017
LIFEBOOK T936/N; LIFEBOOK T936; LIFEBOOK T936/P	V1.12	May 17, 2017
ARROWS Tab Q616/N; STYLISTIC Q616; ARROWS Tab Q616/P	V1.09	May 17, 2017
ARROWS Tab R726/M; ARROWS Tab R726/P; STYLISTIC R726	V1.18	February 01, 2018
LIFEBOOK E557/P; LIFEBOOK E547/P; LIFEBOOK E557; LIFEBOOK E547	V1.11	June 14, 2017
LIFEBOOK S937/P; LIFEBOOK S937/PX; LIFEBOOK S937	V1.05	June 14, 2017
LIFEBOOK U937/P; LIFEBOOK U937	V1.07	June 14, 2017
LIFEBOOK P727/P; LIFEBOOK P727	V1.10	June 14, 2017
LIFEBOOK T937	V1.10	June 14, 2017
LIFEBOOK U727/P; LIFEBOOK U727; LIFEBOOK U757/P; LIFEBOOK U747/P; LIFEBOOK U757; LIFEBOOK U747	V1.14	June 14, 2017
Arrows Tab R727/P; STYLISTIC R727	V1.16	February 23, 2018

