



INTEL Q4 QUARTERLY SECURITY ADVISORY

List of affected Fujitsu Products

In an effort to continuously improve the robustness of the Intel® products, Intel has performed a security review with the objective of continuously enhancing firmware resilience.

Affected Fujitsu products are listed below. For detailed information on the Fujitsu-approved remedy, please refer to the document Intel security vulnerabilities ([INTEL-SA-00185](#) and [INTEL-SA-00191](#)).

Last revised:
Mai 21, 2019

Notes

- This is an overview of affected Fujitsu products.
- This list is updated regularly (affected products, dates and BIOS versions).
- For the supply of an updated BIOS we rely on the support of the component supplier. Further we only can provide fixes for products which are under service. Products which are not listed below are either not affected or out of services.

OEM Mainboard

Affected Mainboard	New BIOS (with Fix)	BIOS release date	New ME (with fix)	ME release date
D3348-B1	yes	t.b.d.	--	--
D3348-B2	yes	t.b.d.	--	--
D3400-B1	--	--	yes	available
D3400-B2	R1.22.0	cw25	--	--
D3401-B1	--	--	yes	available
D3401-B2	R1.22.0	cw25	--	--
D3401-H1	--	--	yes	available
D3401-H2	R1.22.0	cw25	--	--
D3402-B1	--	--	yes	available
D3402-B2	R1.22.0	cw25	--	--
D3410-B1	--	--	yes	available
D3410-B2	R1.22.0	cw25	--	--
D3417-B1	--	--	yes	available
D3417-B2	R1.22.0	cw25	--	--
D3433-S1	--	--	yes	available

D3433-S2	R1.21.0	cw21	--	--
D3434-S1	--	--	yes	available
D3434-S2	R1.21.0	cw21	--	--
D3441-S1	--	--	yes	available
D3441-S2	R1.21.0	cw21	--	--
D3445-K1	--	--	yes	available
D3445-S1	--	--	yes	available
D3446-S1	--	--	yes	available
D3446-S2	R1.21.0	cw21	--	--
D3460-D1	yes	t.b.d.	--	--
D3460-D2	yes	t.b.d.	--	--
D3474-B1	R1.12.0	cw22	--	--
D3480-D1	yes	t.b.d.	--	--
D3480-D2	yes	t.b.d.	--	--
D3543-Sx	R1.10.0	cw24	--	--
D3544-Sx	R1.10.0	cw24	--	--
D3598-B1	R1.8.0	cw24	--	--
D3598-G1	R1.3.0	cw24	--	--
D3674-B1	R1.13.0	available	--	--
D3633-S1	R1.6.0	available	--	--
D3634-S1	R1.6.0	available	--	--
D3641-S1	R1.6.0	available	--	--
D3642-B1	R1.5.0	available	--	--
D3643-H1	R1.5.0	available	--	--
D3644-B1	R1.5.0	available	--	--
D3646-S1	R1.6.0	available	--	--
D3654-B1	R1.5.0	available	--	--

Desktop PC (ESPRIMO)

Affected System	New BIOS (with Fix)	BIOS release date	New ME (with fix)	ME release date
ESPRIMO D556 (E85+;E90+)	--	--	yes	available
ESPRIMO D556 (E94+ PPC)	--	--	yes	available
ESPRIMO D556/2 (E85+;E90+)	R1.22.0	cw25	--	--
ESPRIMO D756 (E85+;E90+;E94+) (Dasa-Q150)	--	--	yes	available
ESPRIMO D757 (E85+;E90+;E94+)	R1.22.0	cw25	--	--
ESPRIMO D956 (E85+;E90+;E94+;LL)	--	--	yes	available
ESPRIMO D957 (E85+;E90+;E94+)	R1.22.0	cw25	--	--
ESPRIMO D958	R1.13.0	available	--	--
ESPRIMO K557 (20", 24")	R1.12.0	cw22	--	--
ESPRIMO K558	R1.15.0	available	--	--
ESPRIMO P556/2	R1.22.0	cw25	--	--
ESPRIMO P556/PH556	--	--	yes	available

ESPRIMO P557	R1.22.0	cw25	--	--
ESPRIMO P558/D558-8L	R1.13.0	available	--	--
ESPRIMO P756 (E85+;E90+;E94+)	--	--	yes	available
ESPRIMO P757 (E85+;E90+;E94+)	R1.22.0	cw25	--	--
ESPRIMO P758/D758-8L	R1.13.0	available	--	--
ESPRIMO P956 (E85+;E90+;E94+;LL)	--	--	yes	available
ESPRIMO P957 (E85+;E90+;E94+;POWER)	R1.22.0	cw25	--	--
ESPRIMO P958	R1.13.0	available	--	--
ESPRIMO Q556	--	--	yes	available
ESPRIMO Q556/2	R1.22.0	cw25	--	--
ESPRIMO Q956	--	--	yes	available
ESPRIMO Q956, Q956/MRE	--	--	yes	available
ESPRIMO Q957, Q957/MRE	R1.22.0	cw25	--	--
ESPRIMO X956	--	--	yes	available

Thin/Future Client PC (FUTRO)

Affected System	New BIOS (with Fix)	BIOS release date	New ME (with fix)	ME release date
FUTRO S540	R1.10.0	cw24	--	--
FUTRO S740	R1.10.0	cw24	--	--
FUTRO S940	R1.10.0	cw24	--	--
IoT Gateway	yes	t.b.d.	--	--

Workstation (CELSIUS)

Affected System	New BIOS (with Fix)	BIOS release date	New ME (with fix)	ME release date
CELSIUS C740	yes	t.b.d.	--	--
CELSIUS C780	R1.2.0	available	--	--
CELSIUS J550	--	--	yes	available
CELSIUS J550/2	R1.22.0	cw25	--	--
CELSIUS J580	R1.13.0	available	--	--
CELSIUS M740/M740 Power	yes	t.b.d.	--	--
CELSIUS M770	R1.8.0	cw24	--	--
CELSIUS R940/R940 Power	yes	t.b.d.	--	--
CELSIUS R970	R1.8.0	cw24	--	--
CELSIUS W550, W550 POWER	--	--	yes	available
CELSIUS W570, POWER, POWER+	R1.22.0	cw25	--	--

Mobile (LIFEBOOK/STYLISTIC/CELSIUS)

Affected System	New BIOS (with Fix)	BIOS release date	New ME (with fix)	ME release date
LIFEBOOK A357	yes	t.b.d.	--	--
LIFEBOOK A556	yes	t.b.d.	--	--
LIFEBOOK A556/G	yes	t.b.d.	--	--
LIFEBOOK A557	yes	t.b.d.	--	--
LIFEBOOK AH557	yes	t.b.d.	--	--
LIFEBOOK E448	yes	cw28	--	--
LIFEBOOK E449	yes	cw28	--	--
LIFEBOOK E458	yes	cw28	--	--
LIFEBOOK E459	yes	cw28	--	--
LIFEBOOK E546	--	--	yes	cw24
LIFEBOOK E547	yes	cw32	--	--
LIFEBOOK E548	yes	cw28	--	--
LIFEBOOK E549	done	from beginning	--	--
LIFEBOOK E556	--	--	yes	cw24
LIFEBOOK E557	yes	cw32	--	--
LIFEBOOK E558	yes	cw28	--	--
LIFEBOOK E559	done	from beginning	--	--
LIFEBOOK E736	--	--	yes	cw24
LIFEBOOK E746	--	--	yes	cw24
LIFEBOOK E756	--	--	yes	cw24
LIFEBOOK P727	V1.16	available	--	--
LIFEBOOK P728	V1.13	available	--	--
LIFEBOOK S936	--	--	yes	cw24
LIFEBOOK S937	V1.11	available	--	--
LIFEBOOK S938	yes	cw27	--	--
LIFEBOOK T726	V1.19	available	--	--
LIFEBOOK T936	V1.19	available	--	--
LIFEBOOK T937	V1.17	available	--	--
LIFEBOOK T938	V1.12	available	--	--
LIFEBOOK T939	done	from beginning	--	--
LIFEBOOK U727	yes	cw32	--	--
LIFEBOOK U728	yes	cw27	--	--
LIFEBOOK U729	done	from beginning	--	--
LIFEBOOK U729X	done	from beginning	--	--
LIFEBOOK U747	yes	cw32	--	--
LIFEBOOK U748	yes	cw27	--	--
LIFEBOOK U749	done	from beginning	--	--
LIFEBOOK U757	yes	cw32	--	--
LIFEBOOK U758	yes	cw27	--	--
LIFEBOOK U759	done	from beginning	--	--
LIFEBOOK U937	V1.14	available	--	--
LIFEBOOK U938	V1.17	available	--	--
LIFEBOOK U939	done	from beginning	--	--

LIFEBOOK U939 (w/TBT)	done	from beginning	--	--
LIFEBOOK U939X	done	from beginning	--	--
LIFEBOOK U939X (w/TBT)	done	from beginning	--	--
STYLISTIC Q616	--	--	yes	cw24
STYLISTIC Q736	--	--	yes	cw24
STYLISTIC Q738	V1.09	available	--	--
STYLISTIC Q739	done	from beginning	--	--
STYLISTIC R726	yes	t.b.d.	--	--
STYLISTIC R727	yes	t.b.d.	--	--
STYLISTIC V727	V1.16	cw23	--	--
CELSIUS H760	--	--	yes	cw24
CELSIUS H770	yes	cw27	--	--
CELSIUS H780	V1.14	available	--	--
CELSIUS H970	V1.15	cw32	--	--
CELSIUS H980	V1.10	available	--	--

Server (PRIMERGY/PRIMEUEST)

Affected System	New BIOS (with Fix)	BIOS release date	New ME/SPS (included in BIOS)
CX 2550M4	1.37.0	available	SPS 04.00.04.393
CX 2560M4	1.37.0	available	SPS 04.00.04.393
CX 2570M4	1.37.0	available	SPS 04.00.04.393
RX 2520M4	1.29.0	available	SPS 04.00.04.393
RX 2530M4	1.29.0	available	SPS 04.00.04.393
RX 2540M4	1.29.0	available	SPS 04.00.04.393
RX 4770M4	1.22.0	available	SPS 04.00.04.393
TX 2550M4	1.29.0	available	SPS 04.00.04.393
PQ3800B	t.b.d	Mid of May	SPS 04.00.04.393

* cw: calendar week

